


**REPAIR OF STERNUM SAW MACHINE FOR THE F.Y 2020-21  
FAISALABAD INSTITUTE OF CARDIOLOGY, FAISALABAD.**

Sr. No.	Description	Qty
1.	(i) Replacement of Shaft Assembly (Complete). (ii) Repair of Sternum Saw Motor Unit. (iii) Repair of Board and winding of Motor. (iv) Replacement of Motor Cover. (v) Service of the complete saw.	01 No.

  
\_\_\_\_\_  
**Medical Superintendent**  
Faisalabad Institute of Cardiology,  
Faisalabad